


Think twice. Work safely.

Personal protection when applying UP resin and gelcoat



Protective overall with hood



Respirator with a protective mask



Chemical gloves




Safety shoes



Personal protection when cutting or sanding cured laminate



Gloves with cut protection



Respirator with a protective mask



Protective overall with hood



Safety shoes



Ensure a safe and clean workplace

Ear muffs or ear plugs when needed



Helmet when needed



Safety glasses when needed



Dust mask when needed



Spot ventilation when possible



Keep your workplace clean



Close lids



Wash your hands after working



Please refer to the UPR Safe Handling Guides at:
<http://www.upresins.org/safe-handling-guides>

The information provided in this poster is correct to the best of our knowledge, information and belief at the date of its publication; it is designed only as a guidance for safe handling, use, and processing. The European UP/VE Resin Association assumes no liability or obligation for the description, designs, and information given herewith.

2017 © European UP/VE Resin Association

UP Resin SG

